# Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BW-KKMP-149-100- 0706H-1

Field Name: ELLSWORTH Well File #: 21737

Date Incident:4/5/2014Time Incident:11:45Facility ID Number:County:MCKENZIETwp:149Rng:100Sec:7Qtr:

**Location Description:** 

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16th St. SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1.2 Mile
Distance Nearest Water Well: 1.2 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 30 Barrels 29.5 Barrels 29.5 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 10/19/2015 Clean Up Concluded: 4/6/2014

Risk Evaluation:

N/A

Areal Extent:

The released produced water was contained in the berm around the AST.

## Potential Environmental Impacts:

The release occurred above ground and was contained in a berm around the AST. A vacuum truck was dispatched to recover the produced water from the berm.

# Action Taken or Planned:

The release occurred above ground and was contained in a berm around the AST. A vacuum truck was dispatched to recover the produced water from the berm.

Wastes Disposal Location: The recovered produced water was disposed of at a properly permitted disposal facility.

Agencies Involved:

## **Updates**

Date: 4/6/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Release, due to tank leak, remained on location within the diking, according to the report. NDIC retains oversight.